

Lake Bennett
Dam Inspection Report
Photographic Documentation
March 4, 2020




1. CREST OF FILL



Looking East



Looking West



Crest of Rock Center



Crest facing upstream

2. UPSTREAM SLOPE



3. DOWNSTREAM SLOPE



4. ABUTMENT CONTACTS



Left



Right

8. PLUNGE BASIN




There is no constructed plunge basin for structure. Outlet is into original stream.

9. EXCAVATED ROCK SPILLWAY



Left Spillway




Right Spillway



Left looking down



Left looking up



Right looking down



Right looking up

Photo's taken at crest of spillways

11. FOUNDATION DRAINAGE



12. RESERVOIR CONTROL



Photo taken above centerline of dam facing upstream. State Park beach is visible.

13. OUTLET CHANNEL



Left outlet



Right outlet

15. AREA BELOW DAM



100' Downstream Lt. Side



100' Downstream CL



100' Downstream Rt. Side